

Summary of Facility Information in the County of Ravalli

Owner Name and Address: The Merc Fresh Market Inc 1000 Main St PO Box 1025 Corvallis MT 59828 Phone: (406) 961-4830

| Sys Fac I | Location Name | Location Street Address | Location City | Zip | Location Phone |
|-----------|---------------------------|-------------------------|---------------|-------|----------------|
| 4102402 | The Merc Fresh Market Inc | 1000 Main St | Corvallis | 59828 | (406) 961-4830 |

| TankID/Alt TankID Status | Tag Numbe | Installed Age/AST | Product Capacity | Tank Mat'l of Construction Secondary Option | Piping Material Secondary Option | Piping Type | Tank Release Detection Piping Release Detection | FR Met Spill/Overl/C |
|-----------------------------|-----------|---------------------|--------------------|--|---------------------------------------|-------------|--|-------------------------|
| 4 / 04 Currently in Use | 376 | 2/1/1994 12 / No | Gasoline 10,000 | STI-P3 None | Fiberglass Reinforced Plastic None | Pressurized | <div> <div>A B C <input checked="" type="radio"/> E F G H <input checked="" type="radio"/> J K L</div> <div>B <input checked="" type="radio"/> E F G H <input checked="" type="radio"/> J K L</div> </div> | Yes Yes Yes Yes |
| 5 / 05 Currently in Use | 377 | 8/1/1996 09 / No | Gasoline 6,000 | Fiberglass Reinforced Plastic None | Fiberglass Reinforced Plastic None | Pressurized | <div> <div>A B C <input checked="" type="radio"/> E F G H <input checked="" type="radio"/> J K L</div> <div>B <input checked="" type="radio"/> E F G H <input checked="" type="radio"/> J K L</div> </div> | Yes Yes Yes Yes |
| 6 / 06 Currently in Use | 378 | 8/1/1996 09 / No | Diesel 4,000 | Fiberglass Reinforced Plastic None | Fiberglass Reinforced Plastic None | Pressurized | <div> <div>A B C <input checked="" type="radio"/> E F G H <input checked="" type="radio"/> J K L</div> <div>B <input checked="" type="radio"/> E F G H <input checked="" type="radio"/> J K L</div> </div> | Yes Yes Yes Yes |

Tank/Piping Release Detection Codes

| | | | | | |
|--------------------------------------|----------------------------|---------------------------|---------------------------------------|------------------------|---------------------|
| A Manual Tank Gauging | C Inventory Control | E Vapor Monitoring | G Interstit. Dbl-Wall Monitor | I SIR | K Deferred |
| B Tank/Line Tightness Testing | D ATG/Auto Line LD | F GW Monitoring | H Interstit. Sec. Con. Monitor | J Other Methods | L Not Listed |

Summary of Facility Information in the County of Ravalli

Owner Name and Address: Floodtide Inc PO Box 508 Darby MT 59829 Phone: (406) 821-1940

| Sys Fac I | Location Name | Location Street Address | Location City | Zip | Location Phone |
|-----------|---------------------|-------------------------|---------------|-------|----------------|
| 4100028 | Mr Ts Food and Fuel | 101 S Main St | Darby | 59829 | (406) 821-1940 |

| TankID/Alt TankID | Tag Numbe | Installed | Product | Tank Mat'l of Construction | Piping Material | Piping Type | Tank Release Detection | FR Met | | | | | | | | | | | | | | | | | | | | | | | | |
|----------------------------|-----------|----------------------|----------------------------------|---------------------------------------|-----------------------------------|----------------------------------|---|---------------|---|---|----------------------------------|---|---|---|---|---|---|---|---|--|---|--|---|---|---|----------------------------------|---|---|---|---|---|--------------------|
| Status | | Age/AST | Capacity | Secondary Option | Secondary Option | | Piping Release Detection | Spill/Overl/C | | | | | | | | | | | | | | | | | | | | | | | | |
| 6 / 06 Currently in Use | 3070 | 4/13/1995 11 / No | Gasoline 12,000 | Fiberglass Reinforced Plastic None | Flexible Plastic Double-Walled | Pressurized | <table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td></td><td>B</td><td></td><td>D</td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table> | A | B | C | <input checked="" type="radio"/> | E | F | G | H | I | J | K | L | | B | | D | E | F | <input checked="" type="radio"/> | H | I | J | K | L | Yes Yes Yes Yes |
| A | B | C | <input checked="" type="radio"/> | E | F | G | H | I | J | K | L | | | | | | | | | | | | | | | | | | | | | |
| | B | | D | E | F | <input checked="" type="radio"/> | H | I | J | K | L | | | | | | | | | | | | | | | | | | | | | |
| 7 / 07 Currently in Use | 3071 | 4/13/1995 11 / No | Gasoline 12,000 | Fiberglass Reinforced Plastic None | Flexible Plastic Double-Walled | Pressurized | <table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td></td><td>B</td><td></td><td>D</td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table> | A | B | C | <input checked="" type="radio"/> | E | F | G | H | I | J | K | L | | B | | D | E | F | <input checked="" type="radio"/> | H | I | J | K | L | Yes Yes Yes Yes |
| A | B | C | <input checked="" type="radio"/> | E | F | G | H | I | J | K | L | | | | | | | | | | | | | | | | | | | | | |
| | B | | D | E | F | <input checked="" type="radio"/> | H | I | J | K | L | | | | | | | | | | | | | | | | | | | | | |

Tank/Piping Release Detection Codes

| | | | | | |
|--------------------------------------|----------------------------|---------------------------|---------------------------------------|------------------------|---------------------|
| A Manual Tank Gauging | C Inventory Control | E Vapor Monitoring | G Interstit. Dbl-Wall Monitor | I SIR | K Deferred |
| B Tank/Line Tightness Testing | D ATG/Auto Line LD | F GW Monitoring | H Interstit. Sec. Con. Monitor | J Other Methods | L Not Listed |

Summary of Facility Information in the County of Ravalli

Owner Name and Address: Darby Lumber Incorporated PO Box 357 Polson MT 59860 Phone: (406) 821-3261

| | | | | | |
|------------------|----------------------|--------------------------------|----------------------|------------|-----------------------|
| Sys Fac I | Location Name | Location Street Address | Location City | Zip | Location Phone |
| 4100853 | Darby Lumber | | Darby | 59829 | |

| TankID/Alt TankID Status | Tag Numbe | Installed Age/AST | Product Capacity | Tank Mat'l of Construction Secondary Option | Piping Material Secondary Option | Piping Type | Tank Release Detection Piping Release Detection | FR Met Spill/Overl/C |
|-----------------------------|-----------|----------------------|---------------------|--|---------------------------------------|--------------|--|-------------------------|
| 4 / 04 Currently in Use | 803 | 4/1/1992 14 / No | Diesel 3,000 | STI-P3 None | Fiberglass Reinforced Plastic None | Safe Suction | <div> <input checked="" type="radio"/>A <input checked="" type="radio"/>B <input checked="" type="radio"/>C <input checked="" type="radio"/>D <input checked="" type="radio"/>E <input checked="" type="radio"/>F <input checked="" type="radio"/>G <input checked="" type="radio"/>H <input checked="" type="radio"/>I <input checked="" type="radio"/>J <input checked="" type="radio"/>K <input checked="" type="radio"/>L </div> | No Yes Yes Yes |
| 5 / 05 Currently in Use | 804 | 4/1/1992 14 / No | Gasoline 1,000 | STI-P3 None | Fiberglass Reinforced Plastic None | Safe Suction | <div> <input checked="" type="radio"/>A <input checked="" type="radio"/>B <input checked="" type="radio"/>C <input checked="" type="radio"/>D <input checked="" type="radio"/>E <input checked="" type="radio"/>F <input checked="" type="radio"/>G <input checked="" type="radio"/>H <input checked="" type="radio"/>I <input checked="" type="radio"/>J <input checked="" type="radio"/>K <input checked="" type="radio"/>L </div> | No Yes Yes Yes |

Tank/Piping Release Detection Codes

| | | | | | |
|--------------------------------------|----------------------------|---------------------------|---------------------------------------|------------------------|---------------------|
| A Manual Tank Gauging | C Inventory Control | E Vapor Monitoring | G Interstit. Dbl-Wall Monitor | I SIR | K Deferred |
| B Tank/Line Tightness Testing | D ATG/Auto Line LD | F GW Monitoring | H Interstit. Sec. Con. Monitor | J Other Methods | L Not Listed |

Summary of Facility Information in the County of Ravalli

Owner Name and Address: Darby School Dist 9 209 School Dr Darby MT 59829 Phone: (406) 821-3974

| Sys Fac I | Location Name | Location Street Address | Location City | Zip | Location Phone |
|-----------|---------------------|-------------------------|---------------|-------|----------------|
| 4109821 | Darby School Dist 9 | 209 School Dr | Darby | 59829 | |

| TankID/Alt TankID | Tag Numbe | Installed Age/AST | Product Capacity | Tank Mat'l of Construction Secondary Option | Piping Material Secondary Option | Piping Type | Tank Release Detection Piping Release Detection | FR Met Spill/Overl/C | | | | | | | | | | | | | | | | | | | | | | | | |
|----------------------------------|-----------|----------------------|----------------------------------|---|---------------------------------------|--------------|--|-------------------------|---|---|---|----------------------------------|---|---|---|---|---|---|---|----------------------------------|--|---|----------------------------------|---|---|---|---|---|---|---|--|-------------------|
| 1 / S2 Temporarily Out of Use | 808 | 3/28/1954 52 / No | Heating Oil 7,700 | Asphalt Coated or Bare Steel Lined Interior/Impressed Curr | Galvanized Steel Impressed Current | U.S. Suction | <table><tr><td>A</td><td>B</td><td>C</td><td>D</td><td><input checked="" type="radio"/></td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td><input checked="" type="radio"/></td><td></td><td>D</td><td><input checked="" type="radio"/></td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td><td></td></tr></table> | A | B | C | D | <input checked="" type="radio"/> | F | G | H | I | J | K | L | <input checked="" type="radio"/> | | D | <input checked="" type="radio"/> | F | G | H | I | J | K | L | | No Yes Yes Yes |
| A | B | C | D | <input checked="" type="radio"/> | F | G | H | I | J | K | L | | | | | | | | | | | | | | | | | | | | | |
| <input checked="" type="radio"/> | | D | <input checked="" type="radio"/> | F | G | H | I | J | K | L | | | | | | | | | | | | | | | | | | | | | | |
| 2 / S1 Temporarily Out of Use | 4504 | 3/28/1974 32 / No | Heating Oil 5,000 | Asphalt Coated or Bare Steel Lined Interior/Impressed Curr | Galvanized Steel Impressed Current | U.S. Suction | <table><tr><td>A</td><td>B</td><td>C</td><td>D</td><td><input checked="" type="radio"/></td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td><input checked="" type="radio"/></td><td></td><td>D</td><td><input checked="" type="radio"/></td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td><td></td></tr></table> | A | B | C | D | <input checked="" type="radio"/> | F | G | H | I | J | K | L | <input checked="" type="radio"/> | | D | <input checked="" type="radio"/> | F | G | H | I | J | K | L | | No Yes Yes Yes |
| A | B | C | D | <input checked="" type="radio"/> | F | G | H | I | J | K | L | | | | | | | | | | | | | | | | | | | | | |
| <input checked="" type="radio"/> | | D | <input checked="" type="radio"/> | F | G | H | I | J | K | L | | | | | | | | | | | | | | | | | | | | | | |

Tank/Piping Release Detection Codes

| | | | | | |
|--------------------------------------|----------------------------|---------------------------|---------------------------------------|------------------------|---------------------|
| A Manual Tank Gauging | C Inventory Control | E Vapor Monitoring | G Interstit. Dbl-Wall Monitor | I SIR | K Deferred |
| B Tank/Line Tightness Testing | D ATG/Auto Line LD | F GW Monitoring | H Interstit. Sec. Con. Monitor | J Other Methods | L Not Listed |

Summary of Facility Information in the County of Ravalli

Owner Name and Address: J & G Properties LLC 1715 North First PO Box 468 Hamilton MT 59840 Phone: (406) 363-5470

| | | | | | |
|------------------|----------------------|--------------------------------|----------------------|------------|-----------------------|
| Sys Fac I | Location Name | Location Street Address | Location City | Zip | Location Phone |
| 4110908 | Oles Country Store 6 | US Highway 93 S | Darby | 59829 | |

| TankID/Alt TankID Status | Tag Numbe | Installed Age/AST | Product Capacity | Tank Mat'l of Construction Secondary Option | Piping Material Secondary Option | Piping Type | Tank Release Detection Piping Release Detection | FR Met Spill/Overl/C |
|----------------------------------|-----------|---------------------|--------------------|--|---------------------------------------|-------------|--|-------------------------|
| 1 / 06 Temporarily Out of Use | 1441 | 4/1/1995 11 / No | Gasoline 12,000 | Fiberglass Reinforced Plastic None | Fiberglass Reinforced Plastic None | Pressurized | <div> <div>A B C D E F G H I J K L</div> <div> <input checked="" type="radio"/> <input checked="" type="radio"/> <input checked="" type="radio"/> <input checked="" type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> </div> </div> | Yes Yes Yes Yes |
| 2 / 07 Temporarily Out of Use | 1442 | 4/1/1995 11 / No | Gasoline 8,000 | Fiberglass Reinforced Plastic None | Fiberglass Reinforced Plastic None | Pressurized | <div> <div>A B C D E F G H I J K L</div> <div> <input checked="" type="radio"/> <input checked="" type="radio"/> <input checked="" type="radio"/> <input checked="" type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> </div> </div> | Yes Yes Yes Yes |
| 3 / 08 Temporarily Out of Use | 1443 | 4/1/1995 11 / No | Diesel 5,000 | Fiberglass Reinforced Plastic None | Fiberglass Reinforced Plastic None | Pressurized | <div> <div>A B C D E F G H I J K L</div> <div> <input checked="" type="radio"/> <input checked="" type="radio"/> <input checked="" type="radio"/> <input checked="" type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> </div> </div> | Yes Yes Yes Yes |

Tank/Piping Release Detection Codes

| | | | | | |
|--------------------------------------|----------------------------|---------------------------|---------------------------------------|------------------------|---------------------|
| A Manual Tank Gauging | C Inventory Control | E Vapor Monitoring | G Interstit. Dbl-Wall Monitor | I SIR | K Deferred |
| B Tank/Line Tightness Testing | D ATG/Auto Line LD | F GW Monitoring | H Interstit. Sec. Con. Monitor | J Other Methods | L Not Listed |

Summary of Facility Information in the County of Ravalli

Owner Name and Address: Cenex Harvest States 4570 N Reserve St Missoula MT 59808 Phone: (406) 543-8383

| Sys Fac I | Location Name | Location Street Address | Location City | Zip | Location Phone |
|-----------|----------------------|-------------------------|---------------|-------|----------------|
| 5614029 | Peoples Market Cenex | 801 N Main St | Darby | 59829 | (406) 543-8383 |

| TankID/Alt TankID Status | Tag Numbe | Installed Age/AST | Product Capacity | Tank Mat'l of Construction Secondary Option | Piping Material Secondary Option | Piping Type | Tank Release Detection Piping Release Detection | FR Met Spill/Overl/C |
|-----------------------------|-----------|----------------------|-------------------|--|-------------------------------------|-------------|--|-------------------------|
| 1 / S1 Currently In Use | 4338 | 8/20/2001 04 / Ye | Gasoline 8,000 | Unknown None | Flexible Plastic Double-Walled | Pressurized | <div> <div>A B C <input checked="" type="radio"/> E F G H I J <input checked="" type="radio"/> L</div> <div>B <input checked="" type="radio"/> E F <input checked="" type="radio"/> H I J K L</div> </div> | Yes Yes Yes Yes |
| 2 / S2 Currently In Use | 4339 | 8/20/2001 04 / Ye | Gasoline 4,000 | Not Listed None | Flexible Plastic Double-Walled | Pressurized | <div> <div>A B C <input checked="" type="radio"/> E F G H I J <input checked="" type="radio"/> L</div> <div>B <input checked="" type="radio"/> E F <input checked="" type="radio"/> H I J K L</div> </div> | Yes Yes Yes Yes |
| 3 / S3 Currently In Use | 4340 | 8/20/2001 04 / Ye | Diesel 5,000 | Not Listed None | Flexible Plastic Double-Walled | Pressurized | <div> <div>A B C <input checked="" type="radio"/> E F G H I J <input checked="" type="radio"/> L</div> <div>B <input checked="" type="radio"/> E F <input checked="" type="radio"/> H I J K L</div> </div> | Yes Yes Yes Yes |
| 4 / S4 Currently In Use | 4341 | 8/20/2001 04 / Ye | Diesel 5,000 | Not Listed None | Flexible Plastic Double-Walled | Pressurized | <div> <div>A B C <input checked="" type="radio"/> E F G H I J <input checked="" type="radio"/> L</div> <div>B <input checked="" type="radio"/> E F <input checked="" type="radio"/> H I J K L</div> </div> | Yes Yes Yes Yes |

Tank/Piping Release Detection Codes

| | | | | | |
|--------------------------------------|----------------------------|---------------------------|---------------------------------------|------------------------|---------------------|
| A Manual Tank Gauging | C Inventory Control | E Vapor Monitoring | G Interstit. Dbl-Wall Monitor | I SIR | K Deferred |
| B Tank/Line Tightness Testing | D ATG/Auto Line LD | F GW Monitoring | H Interstit. Sec. Con. Monitor | J Other Methods | L Not Listed |

Summary of Facility Information in the County of Ravalli

Owner Name and Address: Dyna Mart LLP PO Box 1024 Florence MT 59833 Phone: (406) 273-9993

| Sys Fac I | Location Name | Location Street Address | Location City | Zip | Location Phone |
|-----------|---------------|-------------------------|---------------|-------|----------------|
| 4111356 | Dyna Mart LLP | 5323 US Highway 93 N | Florence | 59833 | (406) 273-9993 |

| TankID/Alt TankID Status | Tag Numbe | Installed Age/AST | Product Capacity | Tank Mat'l of Construction Secondary Option | Piping Material Secondary Option | Piping Type | Tank Release Detection Piping Release Detection | FR Met Spill/Overl/C |
|-----------------------------|-----------|---------------------|--------------------|--|---------------------------------------|-------------|---|-------------------------|
| 1 / S1 Currently in Use | 2331 | 1/1/1980 26 / Ye | Diesel 10,000 | Asphalt Coated or Bare Steel None | Fiberglass Reinforced Plastic None | Pressurized | <div> <div>A B C D E F G H I J K L</div> <div> <input checked="" type="radio"/> <input type="radio"/> E F G H I J K L </div> </div> | Yes Yes Yes Yes |
| 2 / S2 Currently in Use | 2332 | 1/1/1980 26 / Ye | Gasoline 12,000 | Asphalt Coated or Bare Steel None | Fiberglass Reinforced Plastic None | Pressurized | <div> <div>A B C D E F G H I J K L</div> <div> <input checked="" type="radio"/> <input type="radio"/> E F G H I J K L </div> </div> | Yes Yes Yes Yes |
| 3 / S3 Currently in Use | 2333 | 1/1/1980 26 / Ye | Gasoline 12,000 | Asphalt Coated or Bare Steel None | Fiberglass Reinforced Plastic None | Pressurized | <div> <div>A B C D E F G H I J K L</div> <div> <input checked="" type="radio"/> <input type="radio"/> E F G H I J K L </div> </div> | Yes Yes Yes Yes |
| 4 / S4 Currently in Use | 2334 | 1/1/1980 26 / Ye | Gasoline 5,000 | Asphalt Coated or Bare Steel None | Fiberglass Reinforced Plastic None | Pressurized | <div> <div>A B C D E F G H I J K L</div> <div> <input checked="" type="radio"/> <input type="radio"/> E F G H I J K L </div> </div> | Yes Yes Yes Yes |

Tank/Piping Release Detection Codes

| | | | | | |
|--------------------------------------|----------------------------|---------------------------|---------------------------------------|------------------------|---------------------|
| A Manual Tank Gauging | C Inventory Control | E Vapor Monitoring | G Interstit. Dbl-Wall Monitor | I SIR | K Deferred |
| B Tank/Line Tightness Testing | D ATG/Auto Line LD | F GW Monitoring | H Interstit. Sec. Con. Monitor | J Other Methods | L Not Listed |

Summary of Facility Information in the County of Ravalli

Owner Name and Address: Town Pump Inc PO Box 6000 Butte MT 59701 Phone: (406) 497-6700

| Sys Fac I | Location Name | Location Street Address | Location City | Zip | Location Phone |
|-----------|------------------------|-------------------------|---------------|-------|----------------|
| 4112720 | Town Pump Inc Florence | 5495 US Highway 93 N | Florence | 59833 | (406) 273-6685 |

| TankID/Alt TankID Status | Tag Numbe | Installed Age/AST | Product Capacity | Tank Mat'l of Construction Secondary Option | Piping Material Secondary Option | Piping Type | Tank Release Detection Piping Release Detection | FR Met Spill/Overl/C |
|-----------------------------|-----------|---------------------|--------------------|--|---------------------------------------|-------------|---|-------------------------|
| 1 / 01 Currently In Use | 2967 | 1/1/1992 14 / No | Gasoline 9,000 | STI-P3 None | Fiberglass Reinforced Plastic None | Pressurized | <div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div> | Yes Yes Yes Yes |
| 2 / 02 Currently In Use | 2968 | 1/1/1992 14 / No | Diesel 3,000 | STI-P3 None | Fiberglass Reinforced Plastic None | Pressurized | <div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div> | Yes Yes Yes Yes |
| 3 / 03 Currently In Use | 2969 | 1/1/1992 14 / No | Gasoline 6,000 | STI-P3 None | Fiberglass Reinforced Plastic None | Pressurized | <div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div> | Yes Yes Yes Yes |
| 4 / 04 Currently In Use | 2970 | 1/1/1992 14 / No | Gasoline 6,000 | STI-P3 None | Fiberglass Reinforced Plastic None | Pressurized | <div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div> | Yes Yes Yes Yes |
| 5 / 05 Currently In Use | 4192 | 5/1/2000 06 / No | Diesel 5,000 | Fiberglass Reinforced Plastic Double-Walled | Flexible Plastic Double-Walled | Pressurized | <div> <div>A B C <input checked="" type="radio"/> E F <input checked="" type="radio"/> H I J K L</div> <div>B <input checked="" type="radio"/> <input checked="" type="radio"/> E F <input checked="" type="radio"/> H I J K L</div> </div> | Yes Yes Yes Yes |
| 6 / 06 Currently In Use | 4193 | 5/1/2000 06 / No | Gasoline 12,000 | Fiberglass Reinforced Plastic Double-Walled | Flexible Plastic Double-Walled | Pressurized | <div> <div>A B C <input checked="" type="radio"/> E F <input checked="" type="radio"/> H I J K L</div> <div>B <input checked="" type="radio"/> <input checked="" type="radio"/> E F <input checked="" type="radio"/> H I J K L</div> </div> | Yes Yes Yes Yes |
| 7 / 07 Currently In Use | 4194 | 5/1/2000 06 / No | Gasoline 5,000 | Fiberglass Reinforced Plastic Double-Walled | Flexible Plastic Double-Walled | Pressurized | <div> <div>A B C <input checked="" type="radio"/> E F <input checked="" type="radio"/> H I J K L</div> <div>B <input checked="" type="radio"/> <input checked="" type="radio"/> E F <input checked="" type="radio"/> H I J K L</div> </div> | Yes Yes Yes Yes |
| 8 / 08 Currently In Use | 4195 | 5/1/2000 06 / No | Gasoline 10,000 | Fiberglass Reinforced Plastic Double-Walled | Flexible Plastic Double-Walled | Pressurized | <div> <div>A B C <input checked="" type="radio"/> E F <input checked="" type="radio"/> H I J K L</div> <div>B <input checked="" type="radio"/> <input checked="" type="radio"/> E F <input checked="" type="radio"/> H I J K L</div> </div> | Yes Yes Yes Yes |

Tank/Piping Release Detection Codes

| | | | | | |
|--------------------------------------|----------------------------|---------------------------|---------------------------------------|------------------------|---------------------|
| A Manual Tank Gauging | C Inventory Control | E Vapor Monitoring | G Interstit. Dbl-Wall Monitor | I SIR | K Deferred |
| B Tank/Line Tightness Testing | D ATG/Auto Line LD | F GW Monitoring | H Interstit. Sec. Con. Monitor | J Other Methods | L Not Listed |

Summary of Facility Information in the County of Ravalli

| | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
|-----------------------------|--------------------------|------------------|--|-----------------------------------|-------------|---|---|---|---|----------------------------------|---|---|----------------------------------|---|---|---|---|---|---|--|--|----------------------------------|---|---|----------------------------------|---|---|---|---|---|--------------------|
| 9 / 09 Currently In Use | 4196 5/1/2000 06 / No | Diesel 5,000 | Fiberglass Reinforced Plastic Double-Walled | Flexible Plastic Double-Walled | Pressurized | <table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td colspan="3">B</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table> | A | B | C | <input checked="" type="radio"/> | E | F | <input checked="" type="radio"/> | H | I | J | K | L | B | | | <input checked="" type="radio"/> | E | F | <input checked="" type="radio"/> | H | I | J | K | L | Yes Yes Yes Yes |
| A | B | C | <input checked="" type="radio"/> | E | F | <input checked="" type="radio"/> | H | I | J | K | L | | | | | | | | | | | | | | | | | | | | |
| B | | | <input checked="" type="radio"/> | E | F | <input checked="" type="radio"/> | H | I | J | K | L | | | | | | | | | | | | | | | | | | | | |
| 10 / 10 Currently In Use | 4197 5/1/2000 06 / No | Diesel 12,000 | Fiberglass Reinforced Plastic Double-Walled | Flexible Plastic Double-Walled | Pressurized | <table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td colspan="3">B</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table> | A | B | C | <input checked="" type="radio"/> | E | F | <input checked="" type="radio"/> | H | I | J | K | L | B | | | <input checked="" type="radio"/> | E | F | <input checked="" type="radio"/> | H | I | J | K | L | Yes Yes Yes Yes |
| A | B | C | <input checked="" type="radio"/> | E | F | <input checked="" type="radio"/> | H | I | J | K | L | | | | | | | | | | | | | | | | | | | | |
| B | | | <input checked="" type="radio"/> | E | F | <input checked="" type="radio"/> | H | I | J | K | L | | | | | | | | | | | | | | | | | | | | |

Tank/Piping Release Detection Codes

| | | | | | |
|--------------------------------------|----------------------------|---------------------------|---------------------------------------|------------------------|---------------------|
| A Manual Tank Gauging | C Inventory Control | E Vapor Monitoring | G Interstit. Dbl-Wall Monitor | I SIR | K Deferred |
| B Tank/Line Tightness Testing | D ATG/Auto Line LD | F GW Monitoring | H Interstit. Sec. Con. Monitor | J Other Methods | L Not Listed |

Summary of Facility Information in the County of Ravalli

Owner Name and Address: Town Pump Inc PO Box 6000 Butte MT 59701 Phone: (406) 497-6700

| Sys Fac I | Location Name | Location Street Address | Location City | Zip | Location Phone |
|-----------|--------------------------|-------------------------|---------------|-------|----------------|
| 4100145 | Town Pump Inc Hamilton 2 | 932 S 1st St | Hamilton | 59840 | |

| TankID/Alt TankID Status | Tag Numbe | Installed Age/AST | Product Capacity | Tank Mat'l of Construction Secondary Option | Piping Material Secondary Option | Piping Type | Tank Release Detection Piping Release Detection | FR Met Spill/Overl/C |
|-----------------------------|-----------|---------------------|--------------------|---|---------------------------------------|-------------|---|-------------------------|
| 1 / 01 Currently in Use | 2593 | 4/7/1986 20 / No | Gasoline 10,000 | Asphalt Coated or Bare Steel Impressed Current | Galvanized Steel Impressed Current | Pressurized | <div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div> | Yes Yes Yes Yes |
| 2 / 02 Currently in Use | 2594 | 4/7/1984 22 / No | Gasoline 10,000 | Asphalt Coated or Bare Steel Impressed Current | Galvanized Steel Impressed Current | Pressurized | <div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div> | Yes Yes Yes Yes |
| 3 / 03 Currently in Use | 2595 | 4/7/1984 22 / No | Gasoline 6,000 | Asphalt Coated or Bare Steel Impressed Current | Galvanized Steel Impressed Current | Pressurized | <div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div> | Yes Yes Yes Yes |
| 4 / 04 Currently in Use | 2596 | 4/7/1984 22 / No | Diesel 6,000 | Asphalt Coated or Bare Steel Impressed Current | Galvanized Steel Impressed Current | Pressurized | <div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div> | Yes Yes Yes Yes |

Tank/Piping Release Detection Codes

| | | | | | |
|--------------------------------------|----------------------------|---------------------------|---------------------------------------|------------------------|---------------------|
| A Manual Tank Gauging | C Inventory Control | E Vapor Monitoring | G Interstit. Dbl-Wall Monitor | I SIR | K Deferred |
| B Tank/Line Tightness Testing | D ATG/Auto Line LD | F GW Monitoring | H Interstit. Sec. Con. Monitor | J Other Methods | L Not Listed |

Summary of Facility Information in the County of Ravalli

Owner Name and Address: North Side Center Inc 401 N 1st St Hamilton MT 59840 Phone: (406) 363-3711

| Sys Fac I | Location Name | Location Street Address | Location City | Zip | Location Phone |
|-----------|---------------|-------------------------|---------------|-------|----------------|
| 4102138 | Gas N Grub | 401 N 1st St | Hamilton | 59840 | (406) 363-3711 |

| TankID/Alt TankID Status | Tag Numbe | Installed Age/AST | Product Capacity | Tank Mat'l of Construction Secondary Option | Piping Material Secondary Option | Piping Type | Tank Release Detection Piping Release Detection | FR Met Spill/Overl/C |
|-----------------------------|-----------|----------------------|--------------------|---|---------------------------------------|-------------|---|-------------------------|
| 1 / 01 Currently in Use | 1760 | 3/29/1982 24 / No | Gasoline 12,000 | Asphalt Coated or Bare Steel Impressed Current | Bare Steel Impressed Current | Pressurized | <div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div> | Yes Yes Yes Yes |
| 2 / 02 Currently in Use | 1761 | 3/29/1982 24 / No | Gasoline 12,000 | Asphalt Coated or Bare Steel Impressed Current | Bare Steel Impressed Current | Pressurized | <div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div> | Yes Yes Yes Yes |
| 3 / 03 Currently in Use | 1762 | 3/29/1982 24 / No | Gasoline 10,000 | Asphalt Coated or Bare Steel Impressed Current | Fiberglass Reinforced Plastic None | Pressurized | <div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div> | Yes Yes Yes Yes |
| 4 / 04 Currently in Use | 1763 | 3/29/1982 24 / No | Gasoline 4,000 | Asphalt Coated or Bare Steel Impressed Current | Bare Steel Impressed Current | Pressurized | <div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div> | Yes Yes Yes Yes |
| 5 / 05 Currently in Use | 1764 | 3/29/1982 24 / No | Diesel 4,000 | Asphalt Coated or Bare Steel Impressed Current | Bare Steel Impressed Current | Pressurized | <div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div> | Yes Yes Yes Yes |

Tank/Piping Release Detection Codes

| | | | | | |
|--------------------------------------|----------------------------|---------------------------|---------------------------------------|------------------------|---------------------|
| A Manual Tank Gauging | C Inventory Control | E Vapor Monitoring | G Interstit. Dbl-Wall Monitor | I SIR | K Deferred |
| B Tank/Line Tightness Testing | D ATG/Auto Line LD | F GW Monitoring | H Interstit. Sec. Con. Monitor | J Other Methods | L Not Listed |

Summary of Facility Information in the County of Ravalli

Owner Name and Address: Davisons Exxon Service 410 S 1st St Hamilton MT 59840 Phone: (406) 363-1933

| Sys Fac I | Location Name | Location Street Address | Location City | Zip | Location Phone |
|-----------|------------------------|-------------------------|---------------|-------|----------------|
| 4104846 | Davisons Exxon Service | 410 S 1st St | Hamilton | 59840 | (406) 363-1933 |

| TankID/Alt TankID Status | Tag Numbe | Installed Age/AST | Product Capacity | Tank Mat'l of Construction Secondary Option | Piping Material Secondary Option | Piping Type | Tank Release Detection Piping Release Detection | FR Met Spill/Overl/C |
|-----------------------------|-----------|---------------------|-------------------|--|---------------------------------------|-------------|---|-------------------------|
| 5 / S8 Currently in Use | 823 | 3/3/1993 13 / Ye | Diesel 20,000 | Asphalt Coated or Bare Steel None | Fiberglass Reinforced Plastic None | Pressurized | <div> <div>A B C D E F G H I J K L</div> <div> <input checked="" type="radio"/> <input type="radio"/> E F G H I J K L </div> </div> | Yes Yes Yes Yes |
| 6 / S7 Currently in Use | 822 | 3/3/1993 13 / Ye | Gasoline 5,000 | Asphalt Coated or Bare Steel None | Fiberglass Reinforced Plastic None | Pressurized | <div> <div>A B C D E F G H I J K L</div> <div> <input checked="" type="radio"/> <input type="radio"/> E F G H I J K L </div> </div> | Yes Yes Yes Yes |
| 8 / S5 Currently in Use | 821 | 3/1/1993 13 / Ye | Gasoline 2,678 | Asphalt Coated or Bare Steel None | Fiberglass Reinforced Plastic None | Pressurized | <div> <div>A B C D E F G H I J K L</div> <div> <input checked="" type="radio"/> <input type="radio"/> E F G H I J K L </div> </div> | Yes Yes Yes Yes |
| 9 / S4 Currently in Use | 820 | 3/1/1993 13 / Ye | Gasoline 7,050 | Asphalt Coated or Bare Steel None | Fiberglass Reinforced Plastic None | Pressurized | <div> <div>A B C D E F G H I J K L</div> <div> <input checked="" type="radio"/> <input type="radio"/> E F G H I J K L </div> </div> | Yes Yes Yes Yes |

Tank/Piping Release Detection Codes

| | | | | | |
|--------------------------------------|----------------------------|---------------------------|---------------------------------------|------------------------|---------------------|
| A Manual Tank Gauging | C Inventory Control | E Vapor Monitoring | G Interstit. Dbl-Wall Monitor | I SIR | K Deferred |
| B Tank/Line Tightness Testing | D ATG/Auto Line LD | F GW Monitoring | H Interstit. Sec. Con. Monitor | J Other Methods | L Not Listed |

Summary of Facility Information in the County of Ravalli

Owner Name and Address: Anglers Roost LLP 815 US Highway 93 S Hamilton MT 59840 Phone: (406) 363-1268

| Sys Fac I | Location Name | Location Street Address | Location City | Zip | Location Phone |
|-----------|-------------------|-------------------------|---------------|-------|----------------|
| 4105798 | Anglers Roost LLP | 8156 US Highway 93 S | Hamilton | 59840 | (406) 363-1268 |

| TankID/Alt TankID | Tag Numbe | Installed | Product | Tank Mat'l of Construction | Piping Material | Piping Type | Tank Release Detection | FR Met | | | | | | | | | | | | | | | | | | | | | | | | |
|----------------------------|-----------|----------------------|--------------------|---|---------------------------------------|-------------|---|---------------|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|--|--|--------------------|
| Status | | Age/AST | Capacity | Secondary Option | Secondary Option | | Piping Release Detection | Spill/Overl/C | | | | | | | | | | | | | | | | | | | | | | | | |
| 1 / 01 Currently in Use | 3470 | 4/25/1984 22 / No | Gasoline 10,000 | Asphalt Coated or Bare Steel Impressed Current | Galvanized Steel Impressed Current | Pressurized | <table><tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>●</td><td>J</td><td>K</td><td>L</td></tr><tr><td>B</td><td>●</td><td>E</td><td>F</td><td>G</td><td>H</td><td>●</td><td>J</td><td>K</td><td>L</td><td></td><td></td></tr></table> | A | B | C | D | E | F | G | H | ● | J | K | L | B | ● | E | F | G | H | ● | J | K | L | | | Yes Yes Yes Yes |
| A | B | C | D | E | F | G | H | ● | J | K | L | | | | | | | | | | | | | | | | | | | | | |
| B | ● | E | F | G | H | ● | J | K | L | | | | | | | | | | | | | | | | | | | | | | | |
| 2 / 02 Currently in Use | 3471 | 4/4/1985 21 / No | Gasoline 10,000 | Asphalt Coated or Bare Steel Impressed Current | Galvanized Steel Impressed Current | Pressurized | <table><tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>●</td><td>J</td><td>K</td><td>L</td></tr><tr><td>B</td><td>●</td><td>E</td><td>F</td><td>G</td><td>H</td><td>●</td><td>J</td><td>K</td><td>L</td><td></td><td></td></tr></table> | A | B | C | D | E | F | G | H | ● | J | K | L | B | ● | E | F | G | H | ● | J | K | L | | | Yes Yes Yes Yes |
| A | B | C | D | E | F | G | H | ● | J | K | L | | | | | | | | | | | | | | | | | | | | | |
| B | ● | E | F | G | H | ● | J | K | L | | | | | | | | | | | | | | | | | | | | | | | |

Tank/Piping Release Detection Codes

| | | | | | |
|--------------------------------------|----------------------------|---------------------------|---------------------------------------|------------------------|---------------------|
| A Manual Tank Gauging | C Inventory Control | E Vapor Monitoring | G Interstit. Dbl-Wall Monitor | I SIR | K Deferred |
| B Tank/Line Tightness Testing | D ATG/Auto Line LD | F GW Monitoring | H Interstit. Sec. Con. Monitor | J Other Methods | L Not Listed |

Summary of Facility Information in the County of Ravalli

Owner Name and Address: Ravalli County 205 Bedford St Hamilton MT 59840 Phone: (406) 375-6200

| Sys Fac I | Location Name | Location Street Address | Location City | Zip | Location Phone |
|-----------|-----------------------------------|-------------------------|---------------|-------|----------------|
| 4106546 | Ravalli County Road Dept Hamilton | 244 Fairgrounds Road | Hamilton | 59840 | (406) 363-2733 |

| TankID/Alt TankID | Tag Numbe | Installed Age/AST | Product Capacity | Tank Mat'l of Construction Secondary Option | Piping Material Secondary Option | Piping Type | Tank Release Detection | Piping Release Detection | FR Met |
|----------------------------|-----------|----------------------|------------------|---|---------------------------------------|--------------|--|--|--------------------|
| 5 / 05 Currently in Use | 1831 | 11/1/1991 14 / No | Diesel 12,000 | STI-P3 None | Bare Steel Double-Walled/Non-Corro | Safe Suction | <div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F G H I <input checked="" type="radio"/> K L</div> </div> | <div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F G H I <input checked="" type="radio"/> K L</div> </div> | Yes Yes Yes Yes |

Tank/Piping Release Detection Codes

| | | | | | |
|--------------------------------------|----------------------------|---------------------------|---------------------------------------|------------------------|---------------------|
| A Manual Tank Gauging | C Inventory Control | E Vapor Monitoring | G Interstit. Dbl-Wall Monitor | I SIR | K Deferred |
| B Tank/Line Tightness Testing | D ATG/Auto Line LD | F GW Monitoring | H Interstit. Sec. Con. Monitor | J Other Methods | L Not Listed |

Summary of Facility Information in the County of Ravalli

Owner Name and Address: Town Pump Inc PO Box 6000 Butte MT 59701 Phone: (406) 497-6700

| Sys Fac I | Location Name | Location Street Address | Location City | Zip | Location Phone |
|-----------|--------------------------|-------------------------|---------------|-------|----------------|
| 4109670 | Town Pump Inc Hamilton 1 | 1115 N 1st St | Hamilton | 59840 | (406) 363-4643 |

| TankID/Alt TankID Status | Tag Numbe | Installed Age/AST | Product Capacity | Tank Mat'l of Construction Secondary Option | Piping Material Secondary Option | Piping Type | Tank Release Detection Piping Release Detection | FR Met Spill/Overl/C |
|-----------------------------|--------------|----------------------|---------------------|--|---------------------------------------|-------------|--|-------------------------|
| 1 / 01 Currently in Use | 2597 | 2/23/1987 19 / No | Gasoline 12,000 | STI-P3 None | Fiberglass Reinforced Plastic None | Pressurized | <div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div> | Yes Yes Yes Yes |
| 2 / 02 Currently in Use | 2598 | 2/23/1987 19 / No | Gasoline 12,000 | STI-P3 None | Fiberglass Reinforced Plastic None | Pressurized | <div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div> | Yes Yes Yes Yes |
| 3 / 03 Currently in Use | 2599 | 2/23/1987 19 / No | Gasoline 12,000 | STI-P3 None | Fiberglass Reinforced Plastic None | Pressurized | <div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div> | Yes Yes Yes Yes |
| 4 / 05 Currently in Use | 2600 | 2/23/1987 19 / No | Diesel 10,000 | STI-P3 None | Fiberglass Reinforced Plastic None | Pressurized | <div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div> | Yes Yes Yes Yes |
| 5 / 06 Currently In Use | 4490 | 6/1/2001 05 / No | Diesel 10,000 | Fiberglass Reinforced Plastic Double-Walled | Flexible Plastic Double-Walled | Pressurized | <div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B <input checked="" type="radio"/> <input checked="" type="radio"/> E F <input checked="" type="radio"/> H I J K L</div> </div> | Yes Yes Yes Yes |
| 6 / 07 Currently In Use | 4491 | 6/1/2001 05 / No | Diesel 5,000 | Fiberglass Reinforced Plastic Double-Walled | Flexible Plastic Double-Walled | Pressurized | <div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B <input checked="" type="radio"/> <input checked="" type="radio"/> E F <input checked="" type="radio"/> H I J K L</div> </div> | Yes Yes Yes Yes |

Tank/Piping Release Detection Codes

| | | | | | |
|--------------------------------------|----------------------------|---------------------------|---------------------------------------|------------------------|---------------------|
| A Manual Tank Gauging | C Inventory Control | E Vapor Monitoring | G Interstit. Dbl-Wall Monitor | I SIR | K Deferred |
| B Tank/Line Tightness Testing | D ATG/Auto Line LD | F GW Monitoring | H Interstit. Sec. Con. Monitor | J Other Methods | L Not Listed |

Summary of Facility Information in the County of Ravalli

Owner Name and Address: Charles Beigarten 2079 Pulsar Ave Livermore CA 94550 Phone: (925) 449-7946

| Sys Fac I | Location Name | Location Street Address | Location City | Zip | Location Phone |
|-----------|---------------------------------|-------------------------|---------------|-------|----------------|
| 4110864 | Oles Country Store Inc Hamilton | 501 S 1st St | Hamilton | 59840 | (406) 363-6375 |

| TankID/Alt TankID Status | Tag Numbe | Installed Age/AST | Product Capacity | Tank Mat'l of Construction Secondary Option | Piping Material Secondary Option | Piping Type | Tank Release Detection Piping Release Detection | FR Met Spill/Overl/C |
|----------------------------------|-----------|----------------------|-------------------|--|---------------------------------------|-------------|--|-------------------------|
| 4 / 04 Temporarily Out of Use | 2707 | 10/1/1991 14 / No | Gasoline 8,000 | Cathodically Protected Steel None | Fiberglass Reinforced Plastic None | Pressurized | <div> <div>A●●●EFGHIJKL</div> <div>●●EFGHIJKL</div> </div> | Yes Yes Yes Yes |
| 5 / 05 Temporarily Out of Use | 2708 | 10/1/1991 14 / No | Gasoline 8,000 | Cathodically Protected Steel None | Fiberglass Reinforced Plastic None | Pressurized | <div> <div>A●●●EFGHIJKL</div> <div>●●EFGHIJKL</div> </div> | Yes Yes Yes Yes |
| 6 / 06 Temporarily Out of Use | 2709 | 10/1/1991 14 / No | Gasoline 4,000 | Cathodically Protected Steel None | Fiberglass Reinforced Plastic None | Pressurized | <div> <div>A●●●EFGHIJKL</div> <div>●●EFGHIJKL</div> </div> | Yes Yes Yes Yes |

Tank/Piping Release Detection Codes

| | | | | | |
|--------------------------------------|----------------------------|---------------------------|---------------------------------------|------------------------|---------------------|
| A Manual Tank Gauging | C Inventory Control | E Vapor Monitoring | G Interstit. Dbl-Wall Monitor | I SIR | K Deferred |
| B Tank/Line Tightness Testing | D ATG/Auto Line LD | F GW Monitoring | H Interstit. Sec. Con. Monitor | J Other Methods | L Not Listed |

Summary of Facility Information in the County of Ravalli

Owner Name and Address: West Fork Holdings LLC 1987 N 1st St Hamilton MT 59840 Phone: (406) 375-0536

| Sys Fac I | Location Name | Location Street Address | Location City | Zip | Location Phone |
|-----------|------------------|-------------------------|---------------|-------|----------------|
| 4113588 | Riverside Conoco | 1987 N 1st St | Hamilton | 59840 | (406) 363-3703 |

| TankID/Alt TankID Status | Tag Numbe | Installed Age/AST | Product Capacity | Tank Mat'l of Construction Secondary Option | Piping Material Secondary Option | Piping Type | Tank Release Detection Piping Release Detection | FR Met Spill/Overl/C |
|-----------------------------|-----------|----------------------|--------------------|--|-------------------------------------|--------------|--|-------------------------|
| 2 / 02 Currently In Use | 3262 | 6/1/1998 08 / No | Gasoline 12,000 | Fiberglass Reinforced Plastic None | Flexible Plastic Double-Walled | Pressurized | <div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div> | Yes Yes Yes Yes |
| 3 / 03 Currently In Use | 3263 | 6/1/1998 08 / No | Gasoline 8,000 | Fiberglass Reinforced Plastic None | Flexible Plastic Double-Walled | Pressurized | <div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div> | Yes Yes Yes Yes |
| 4 / 04 Currently In Use | 3264 | 6/1/1998 08 / No | Diesel 4,000 | Fiberglass Reinforced Plastic None | Flexible Plastic Double-Walled | Pressurized | <div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div> | Yes Yes Yes Yes |
| 5 / 05 Currently In Use | 5061 | 12/7/2005 00 / No | Diesel 8,000 | Fiberglass Reinforced Plastic None | Flexible Plastic Double-Walled | U.S. Suction | <div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div> | Yes Yes Yes Yes |

Tank/Piping Release Detection Codes

| | | | | | |
|--------------------------------------|----------------------------|---------------------------|---------------------------------------|------------------------|---------------------|
| A Manual Tank Gauging | C Inventory Control | E Vapor Monitoring | G Interstit. Dbl-Wall Monitor | I SIR | K Deferred |
| B Tank/Line Tightness Testing | D ATG/Auto Line LD | F GW Monitoring | H Interstit. Sec. Con. Monitor | J Other Methods | L Not Listed |

Summary of Facility Information in the County of Ravalli

Owner Name and Address: Wanda Dakolios Mickey 501 E Lake Mead Pkwy Apt 2514 Henderson NV 89015 Phone: (702) 564-7637

| | | | | | |
|------------------|----------------------|--------------------------------|----------------------|------------|-----------------------|
| Sys Fac I | Location Name | Location Street Address | Location City | Zip | Location Phone |
| 4113769 | Mickeys Fast Lube | 400 N 1st St | Hamilton | 59840 | |

| TankID/Alt TankID Status | Tag Numbe | Installed Age/AST | Product Capacity | Tank Mat'l of Construction Secondary Option | Piping Material Secondary Option | Piping Type | Tank Release Detection Piping Release Detection | FR Met Spill/Overl/C |
|----------------------------------|-----------|---------------------|--------------------|--|--|-------------|---|-------------------------|
| 1 / 01 Temporarily Out of Use | 3436 | 3/5/1997 09 / No | Gasoline 12,000 | Fiberglass Reinforced Plastic None | Fiberglass Reinforced Plastic Double-Walled | Pressurized | <div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B <input checked="" type="radio"/> E F <input checked="" type="radio"/> H I J K L</div> </div> | No Yes Yes Yes |
| 2 / 02 Temporarily Out of Use | 3437 | 3/5/1997 09 / No | Gasoline 8,000 | Fiberglass Reinforced Plastic None | Fiberglass Reinforced Plastic Double-Walled | Pressurized | <div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B <input checked="" type="radio"/> E F <input checked="" type="radio"/> H I J K L</div> </div> | No Yes Yes Yes |
| 3 / 03 Temporarily Out of Use | 3438 | 3/5/1997 09 / No | Diesel 4,000 | Fiberglass Reinforced Plastic None | Fiberglass Reinforced Plastic Double-Walled | Pressurized | <div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B <input checked="" type="radio"/> E F <input checked="" type="radio"/> H I J K L</div> </div> | No Yes Yes Yes |

Tank/Piping Release Detection Codes

| | | | | | |
|--------------------------------------|----------------------------|---------------------------|---------------------------------------|------------------------|---------------------|
| A Manual Tank Gauging | C Inventory Control | E Vapor Monitoring | G Interstit. Dbl-Wall Monitor | I SIR | K Deferred |
| B Tank/Line Tightness Testing | D ATG/Auto Line LD | F GW Monitoring | H Interstit. Sec. Con. Monitor | J Other Methods | L Not Listed |

Summary of Facility Information in the County of Ravalli

Owner Name and Address: West Fork Holdings 594 Sunny Ln Hamilton MT 59840 Phone: (406) 363-6844

| Sys Fac I | Location Name | Location Street Address | Location City | Zip | Location Phone |
|-----------|---------------|-------------------------|---------------|-------|----------------|
| 5613874 | Lone Pine Inc | 504 US Highway 93 S | Hamilton | 59840 | |

| TankID/Alt TankID Status | Tag Numbe | Installed Age/AST | Product Capacity | Tank Mat'l of Construction Secondary Option | Piping Material Secondary Option | Piping Type | Tank Release Detection Piping Release Detection | FR Met Spill/Overl/C |
|-----------------------------|-----------|---------------------|--------------------|--|-------------------------------------|-------------|--|-------------------------|
| 1 / 01 Currently In Use | 3513 | 7/1/1998 08 / No | Gasoline 10,000 | Fiberglass Reinforced Plastic None | Flexible Plastic Double-Walled | Pressurized | <div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div> | Yes Yes Yes Yes |
| 2 / 02 Currently In Use | 3514 | 7/1/1998 08 / No | Gasoline 8,000 | Fiberglass Reinforced Plastic None | Flexible Plastic Double-Walled | Pressurized | <div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div> | Yes Yes Yes Yes |
| 3 / 03 Currently In Use | 3515 | 7/1/1998 08 / No | Diesel 4,000 | Fiberglass Reinforced Plastic None | Flexible Plastic Double-Walled | Pressurized | <div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div> | Yes Yes Yes Yes |

Tank/Piping Release Detection Codes

| | | | | | |
|--------------------------------------|----------------------------|---------------------------|---------------------------------------|------------------------|---------------------|
| A Manual Tank Gauging | C Inventory Control | E Vapor Monitoring | G Interstit. Dbl-Wall Monitor | I SIR | K Deferred |
| B Tank/Line Tightness Testing | D ATG/Auto Line LD | F GW Monitoring | H Interstit. Sec. Con. Monitor | J Other Methods | L Not Listed |

Summary of Facility Information in the County of Ravalli

Owner Name and Address: Three Mile Trading Co 899 Three Mile Creek Road Stevensville MT 59870 Phone: (406) 777-3365

| Sys Fac I | Location Name | Location Street Address | Location City | Zip | Location Phone |
|-----------|-----------------------|-------------------------|---------------|-------|----------------|
| 4100170 | Three Mile Trading Co | 899 3 Mile Creek Road | Stevensville | 59870 | (406) 777-3365 |

| TankID/Alt TankID Status | Tag Numbe | Installed Age/AST | Product Capacity | Tank Mat'l of Construction Secondary Option | Piping Material Secondary Option | Piping Type | Tank Release Detection Piping Release Detection | FR Met Spill/Overl/C |
|-----------------------------|-----------|---------------------|-------------------|--|--|--------------|--|-------------------------|
| 1 / 05 Currently in Use | 2117 | 3/1/1993 13 / No | Gasoline 2,000 | Cathodically Protected Steel None | Galvanized Steel Cathodically Protected | Safe Suction | <div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F G H I <input checked="" type="radio"/> K L</div> </div> | Yes Yes Yes Yes |
| 2 / 04 Currently in Use | 2116 | 3/1/1993 13 / No | Diesel 5,000 | Cathodically Protected Steel None | Galvanized Steel Cathodically Protected | Safe Suction | <div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F G H I <input checked="" type="radio"/> K L</div> </div> | Yes Yes Yes Yes |
| 4 / 03 Currently in Use | 2115 | 3/1/1993 13 / No | Gasoline 5,000 | Cathodically Protected Steel None | Galvanized Steel Cathodically Protected | Safe Suction | <div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F G H I <input checked="" type="radio"/> K L</div> </div> | Yes Yes Yes Yes |

Tank/Piping Release Detection Codes

| | | | | | |
|--------------------------------------|----------------------------|---------------------------|---------------------------------------|------------------------|---------------------|
| A Manual Tank Gauging | C Inventory Control | E Vapor Monitoring | G Interstit. Dbl-Wall Monitor | I SIR | K Deferred |
| B Tank/Line Tightness Testing | D ATG/Auto Line LD | F GW Monitoring | H Interstit. Sec. Con. Monitor | J Other Methods | L Not Listed |

Summary of Facility Information in the County of Ravalli

Owner Name and Address: Rainforth Corp 2693 Eastside Highway Stevensville MT 59870 Phone: (406) 777-5672

| Sys Fac I | Location Name | Location Street Address | Location City | Zip | Location Phone |
|-----------|---------------|-------------------------|---------------|-------|----------------|
| 4110286 | Caseys Store | 2693 Eastside Highway | Stevensville | 59870 | (406) 777-9894 |

| TankID/Alt TankID Status | Tag Numbe | Installed Age/AST | Product Capacity | Tank Mat'l of Construction Secondary Option | Piping Material Secondary Option | Piping Type | Tank Release Detection Piping Release Detection | FR Met Spill/Overl/C |
|-----------------------------|-----------|----------------------|-------------------|--|-------------------------------------|-------------|--|-------------------------|
| 3 / S3 Currently In Use | 3614 | 12/1/1998 07 / Ye | Gasoline 6,000 | Unknown None | Flexible Plastic Double-Walled | Pressurized | <div> <div>A B C D E F G H I J K L</div> <div>B ● E F ● H I J K L</div> </div> | Yes Yes Yes Yes |
| 4 / S4 Currently In Use | 3615 | 12/1/1998 07 / Ye | Diesel 3,000 | Unknown None | Flexible Plastic Double-Walled | Pressurized | <div> <div>A B C D E F G H I J K L</div> <div>B ● E F ● H I J K L</div> </div> | Yes Yes Yes Yes |
| 5 / S5 Currently In Use | 3809 | 12/1/1998 07 / Ye | Diesel 3,000 | Unknown None | Flexible Plastic Double-Walled | Pressurized | <div> <div>A B C D E F G H I J K L</div> <div>B ● E F ● H I J K L</div> </div> | Yes Yes Yes Yes |

Tank/Piping Release Detection Codes

| | | | | | |
|--------------------------------------|----------------------------|---------------------------|---------------------------------------|------------------------|---------------------|
| A Manual Tank Gauging | C Inventory Control | E Vapor Monitoring | G Interstit. Dbl-Wall Monitor | I SIR | K Deferred |
| B Tank/Line Tightness Testing | D ATG/Auto Line LD | F GW Monitoring | H Interstit. Sec. Con. Monitor | J Other Methods | L Not Listed |

Summary of Facility Information in the County of Ravalli

Owner Name and Address: Cenex Harvest States 4570 N Reserve St Missoula MT 59808 Phone: (406) 543-8383

| Sys Fac I | Location Name | Location Street Address | Location City | Zip | Location Phone |
|-----------|---------------------|-------------------------|---------------|-------|----------------|
| 4110330 | Mountain West Co Op | 115 Main St | Stevensville | 59870 | (406) 777-5441 |

| TankID/Alt TankID | Tag Numbe | Installed | Product | Tank Mat'l of Construction | Piping Material | Piping Type | Tank Release Detection | FR Met | | | | | | | | | | | | | | | | | | | | | | | | |
|----------------------------------|----------------------------------|----------------------------------|----------------------------------|---|---------------------------------------|----------------------------------|--|----------------------------------|----------------------------------|----------------------------------|----------------------------------|---|---|---|---|---|---|---|---|----------------------------------|----------------------------------|----------------------------------|----------------------------------|----------------------------------|----------------------------------|----------------------------------|----------------------------------|----------------------------------|----------------------------------|----------------------------------|----------------------------------|--------------------|
| Status | | Age/AST | Capacity | Secondary Option | Secondary Option | | Piping Release Detection | Spill/Overl/C | | | | | | | | | | | | | | | | | | | | | | | | |
| 1 / 06 Currently in Use | 911 | 2/14/1978 28 / No | Diesel 15,000 | Cathodically Protected Steel Lined Interior/Impressed Curr | Bare Steel Cathodically Protected | Pressurized | <table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td></tr></table> | A | B | C | <input checked="" type="radio"/> | E | F | G | H | I | J | K | L | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | Yes Yes Yes Yes |
| A | B | C | <input checked="" type="radio"/> | E | F | G | H | I | J | K | L | | | | | | | | | | | | | | | | | | | | | |
| <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | | | | | | | | | | | | | | | | | | | | | |
| 2 / 04 Currently in Use | 909 | 2/14/1978 28 / No | Gasoline 10,000 | Cathodically Protected Steel Lined Interior/Impressed Curr | Bare Steel Cathodically Protected | Pressurized | <table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td></tr></table> | A | B | C | <input checked="" type="radio"/> | E | F | G | H | I | J | K | L | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | Yes Yes Yes Yes |
| A | B | C | <input checked="" type="radio"/> | E | F | G | H | I | J | K | L | | | | | | | | | | | | | | | | | | | | | |
| <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | | | | | | | | | | | | | | | | | | | | | |
| 3 / 05 Currently in Use | 910 | 2/14/1978 28 / No | Gasoline 15,000 | Cathodically Protected Steel Lined Interior/Impressed Curr | Bare Steel Cathodically Protected | Pressurized | <table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td></tr></table> | A | B | C | <input checked="" type="radio"/> | E | F | G | H | I | J | K | L | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | Yes Yes Yes Yes |
| A | B | C | <input checked="" type="radio"/> | E | F | G | H | I | J | K | L | | | | | | | | | | | | | | | | | | | | | |
| <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | | | | | | | | | | | | | | | | | | | | | |
| 4 / 02 Currently in Use | 907 | 2/14/1978 28 / No | Diesel 15,000 | Cathodically Protected Steel Lined Interior/Impressed Curr | Bare Steel Cathodically Protected | Pressurized | <table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td></tr></table> | A | B | C | <input checked="" type="radio"/> | E | F | G | H | I | J | K | L | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | Yes Yes Yes Yes |
| A | B | C | <input checked="" type="radio"/> | E | F | G | H | I | J | K | L | | | | | | | | | | | | | | | | | | | | | |
| <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | | | | | | | | | | | | | | | | | | | | | |
| 5 / 03 Currently in Use | 908 | 2/14/1978 28 / No | Gasoline 15,000 | Cathodically Protected Steel Lined Interior/Impressed Curr | Bare Steel Cathodically Protected | Pressurized | <table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td></tr></table> | A | B | C | <input checked="" type="radio"/> | E | F | G | H | I | J | K | L | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | Yes Yes Yes Yes |
| A | B | C | <input checked="" type="radio"/> | E | F | G | H | I | J | K | L | | | | | | | | | | | | | | | | | | | | | |
| <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | | | | | | | | | | | | | | | | | | | | | |
| 6 / 01 Currently in Use | 906 | 2/14/1978 28 / No | Gasoline 15,000 | Cathodically Protected Steel Lined Interior/Impressed Curr | Bare Steel Cathodically Protected | Pressurized | <table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td></tr></table> | A | B | C | <input checked="" type="radio"/> | E | F | G | H | I | J | K | L | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | Yes Yes Yes Yes |
| A | B | C | <input checked="" type="radio"/> | E | F | G | H | I | J | K | L | | | | | | | | | | | | | | | | | | | | | |
| <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | | | | | | | | | | | | | | | | | | | | | |
| 7 / 07 Currently In Use | 912 | 12/29/1997 08 / No | Diesel 10,000 | Fiberglass Reinforced Plastic None | Fiberglass Reinforced Plastic None | Pressurized | <table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td></tr></table> | A | B | C | <input checked="" type="radio"/> | E | F | G | H | I | J | K | L | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | Yes Yes Yes Yes |
| A | B | C | <input checked="" type="radio"/> | E | F | G | H | I | J | K | L | | | | | | | | | | | | | | | | | | | | | |
| <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | | | | | | | | | | | | | | | | | | | | | |

Tank/Piping Release Detection Codes

| | | | | | |
|--------------------------------------|----------------------------|---------------------------|---------------------------------------|------------------------|---------------------|
| A Manual Tank Gauging | C Inventory Control | E Vapor Monitoring | G Interstit. Dbl-Wall Monitor | I SIR | K Deferred |
| B Tank/Line Tightness Testing | D ATG/Auto Line LD | F GW Monitoring | H Interstit. Sec. Con. Monitor | J Other Methods | L Not Listed |

Summary of Facility Information in the County of Ravalli

Owner Name and Address: Steven Clevidence 324 Main St Stevensville MT 59870 Phone: (406) 642-3890

| Sys Fac I | Location Name | Location Street Address | Location City | Zip | Location Phone |
|-----------|--------------------|-------------------------|---------------|-------|----------------|
| 4111429 | The Works Sinclair | 324 Main St | Stevensville | 59870 | |

| TankID/Alt TankID Status | Tag Numbe | Installed Age/AST | Product Capacity | Tank Mat'l of Construction Secondary Option | Piping Material Secondary Option | Piping Type | Tank Release Detection Piping Release Detection | FR Met Spill/Overl/C |
|-----------------------------|-----------|-----------------------|-------------------|--|---------------------------------------|--------------|--|-------------------------|
| 1 / 05 Currently in Use | 2346 | 10/28/1990 15 / No | Gasoline 6,000 | STI-P3 None | Fiberglass Reinforced Plastic None | U.S. Suction | <div> <div>A B C <input checked="" type="radio"/> D <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> D E F G H I J K L</div> </div> | Yes Yes Yes Yes |
| 2 / 06 Currently in Use | 2347 | 10/28/1990 15 / No | Gasoline 6,000 | STI-P3 None | Fiberglass Reinforced Plastic None | U.S. Suction | <div> <div>A B C <input checked="" type="radio"/> D <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> D E F G H I J K L</div> </div> | Yes Yes Yes Yes |
| 3 / 07 Currently in Use | 2348 | 10/28/1990 15 / No | Gasoline 2,000 | STI-P3 None | Fiberglass Reinforced Plastic None | U.S. Suction | <div> <div>A B C <input checked="" type="radio"/> D <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> D <input checked="" type="radio"/> E F G H I J K L</div> </div> | Yes Yes Yes Yes |

Tank/Piping Release Detection Codes

| | | | | | |
|--------------------------------------|----------------------------|---------------------------|---------------------------------------|------------------------|---------------------|
| A Manual Tank Gauging | C Inventory Control | E Vapor Monitoring | G Interstit. Dbl-Wall Monitor | I SIR | K Deferred |
| B Tank/Line Tightness Testing | D ATG/Auto Line LD | F GW Monitoring | H Interstit. Sec. Con. Monitor | J Other Methods | L Not Listed |

Summary of Facility Information in the County of Ravalli

Owner Name and Address: Ralls Inc 3912 US Highway 93 N Stevensville MT 59870 Phone: (406) 777-1179

| Sys Fac I | Location Name | Location Street Address | Location City | Zip | Location Phone |
|-----------|-----------------------|-------------------------|---------------|-------|----------------|
| 4113686 | Oles Country Store 15 | 3912 US Highway 93 N | Stevensville | 59870 | (406) 777-1179 |

| TankID/Alt TankID Status | Tag Numbe | Installed Age/AST | Product Capacity | Tank Mat'l of Construction Secondary Option | Piping Material Secondary Option | Piping Type | Tank Release Detection Piping Release Detection | FR Met Spill/Overl/C |
|-----------------------------|-----------|----------------------|--------------------|--|-------------------------------------|-------------|--|-------------------------|
| 1 / 01 Currently in Use | 3316 | 5/1/1996 10 / No | Gasoline 12,000 | Fiberglass Reinforced Plastic Double-Walled | Flexible Plastic Double-Walled | Pressurized | <div> <div>A B C <input checked="" type="radio"/> E F <input checked="" type="radio"/> H I J K L</div> <div>B <input checked="" type="radio"/> E F <input checked="" type="radio"/> H I J K L</div> </div> | Yes Yes Yes Yes |
| 2 / 02 Currently in Use | 3317 | 5/17/1996 10 / No | Gasoline 8,000 | Fiberglass Reinforced Plastic Double-Walled | Flexible Plastic Double-Walled | Pressurized | <div> <div>A B C <input checked="" type="radio"/> E F <input checked="" type="radio"/> H I J K L</div> <div>B <input checked="" type="radio"/> E F <input checked="" type="radio"/> H I J K L</div> </div> | Yes Yes Yes Yes |
| 3 / 03 Currently in Use | 3318 | 5/17/1996 10 / No | Diesel 3,000 | Fiberglass Reinforced Plastic Double-Walled | Flexible Plastic Double-Walled | Pressurized | <div> <div>A B C <input checked="" type="radio"/> E F <input checked="" type="radio"/> H I J K L</div> <div>B <input checked="" type="radio"/> E F <input checked="" type="radio"/> H I J K L</div> </div> | Yes Yes Yes Yes |

Tank/Piping Release Detection Codes

| | | | | | |
|--------------------------------------|----------------------------|---------------------------|---------------------------------------|------------------------|---------------------|
| A Manual Tank Gauging | C Inventory Control | E Vapor Monitoring | G Interstit. Dbl-Wall Monitor | I SIR | K Deferred |
| B Tank/Line Tightness Testing | D ATG/Auto Line LD | F GW Monitoring | H Interstit. Sec. Con. Monitor | J Other Methods | L Not Listed |

Summary of Facility Information in the County of Ravalli

Owner Name and Address: Sula Store LLC 7060 US Highway 93 S Sula MT 59871 Phone: (406) 821-1041

| Sys Fac I | Location Name | Location Street Address | Location City | Zip | Location Phone |
|-----------|------------------------|-------------------------|---------------|-------|----------------|
| 4110411 | Sula Country Store LLC | 7060 US Highway 93 S | Sula | 59871 | (406) 821-1041 |

| TankID/Alt TankID Status | Tag Numbe | Installed Age/AST | Product Capacity | Tank Mat'l of Construction Secondary Option | Piping Material Secondary Option | Piping Type | Tank Release Detection Piping Release Detection | FR Met Spill/Overl/C |
|-----------------------------|-----------|---------------------|--------------------|--|-------------------------------------|-------------|--|-------------------------|
| 3 / 03 Currently In Use | 3485 | 3/1/1998 08 / No | Gasoline 12,000 | Fiberglass Reinforced Plastic None | Flexible Plastic Double-Walled | Pressurized | <div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div> | Yes Yes Yes Yes |
| 4 / 04 Currently In Use | 3486 | 3/1/1998 08 / No | Gasoline 5,000 | Fiberglass Reinforced Plastic None | Flexible Plastic Double-Walled | Pressurized | <div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div> | Yes Yes Yes Yes |
| 5 / 05 Currently In Use | 3487 | 3/1/1998 08 / No | Gasoline 8,000 | Fiberglass Reinforced Plastic None | Flexible Plastic Double-Walled | Pressurized | <div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div> | Yes Yes Yes Yes |

Tank/Piping Release Detection Codes

| | | | | | |
|--------------------------------------|----------------------------|---------------------------|---------------------------------------|------------------------|---------------------|
| A Manual Tank Gauging | C Inventory Control | E Vapor Monitoring | G Interstit. Dbl-Wall Monitor | I SIR | K Deferred |
| B Tank/Line Tightness Testing | D ATG/Auto Line LD | F GW Monitoring | H Interstit. Sec. Con. Monitor | J Other Methods | L Not Listed |

Summary of Facility Information in the County of Ravalli

Owner Name and Address: Lost Trail Ski Area Inc PO Box 311 Conner MT 59827 Phone: (406) 821-3211

| Sys Fac I | Location Name | Location Street Address | Location City | Zip | Location Phone |
|-----------|----------------------------|-------------------------|---------------|-------|----------------|
| 4111692 | Lost Trail Powder Mountain | 7674 US Highway 93 S | Sula | 59871 | (406) 821-3508 |

| TankID/Alt TankID Status | Tag Numbe | Installed Age/AST | Product Capacity | Tank Mat'l of Construction Secondary Option | Piping Material Secondary Option | Piping Type | Tank Release Detection Piping Release Detection | FR Met Spill/Overl/C |
|-----------------------------|-----------|----------------------|------------------|--|-------------------------------------|--------------|---|-------------------------|
| 1 / 01 Currently in Use | 2351 | 1/1/1990 16 / No | Diesel 8,000 | STI-P3 None | No Piping None | Gravity Feed | <div> <div>A B C D E F G H I J K L</div> <div>B D E F G H I J K L</div> </div> | Yes Yes Yes Yes |
| 2 / 02 Currently in Use | 2352 | 10/1/1992 13 / No | Diesel 8,000 | Composite (Steel w/ FRP) None | No Piping None | Pressurized | <div> <div>A B C D E F G H I J K L</div> <div>B D E F G H I J K L</div> </div> | Yes Yes Yes Yes |

Tank/Piping Release Detection Codes

| | | | | | |
|--------------------------------------|----------------------------|---------------------------|---------------------------------------|------------------------|---------------------|
| A Manual Tank Gauging | C Inventory Control | E Vapor Monitoring | G Interstit. Dbl-Wall Monitor | I SIR | K Deferred |
| B Tank/Line Tightness Testing | D ATG/Auto Line LD | F GW Monitoring | H Interstit. Sec. Con. Monitor | J Other Methods | L Not Listed |

Summary of Facility Information in the County of Ravalli

Owner Name and Address: A & L Robinson Inc 2381 Highway 93 PO Box 760 Victor MT 59875 Phone: (406) 642-3597

| Sys Fac I | Location Name | Location Street Address | Location City | Zip | Location Phone |
|-----------|---------------|-------------------------|---------------|-------|----------------|
| 4113288 | Victor Exxon | 2381 US Highway 93 N | Victor | 59875 | (406) 363-7079 |

| TankID/Alt TankID Status | Tag Numbe | Installed Age/AST | Product Capacity | Tank Mat'l of Construction Secondary Option | Piping Material Secondary Option | Piping Type | Tank Release Detection Piping Release Detection | FR Met Spill/Overl/C |
|-----------------------------|-----------|----------------------|--------------------|--|---------------------------------------|-------------|---|-------------------------|
| 1 / 01 Currently in Use | 3174 | 11/1/1993 12 / No | Gasoline 10,000 | Fiberglass Reinforced Plastic None | Fiberglass Reinforced Plastic None | Pressurized | <div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div> | Yes Yes Yes Yes |
| 2 / 02 Currently in Use | 3175 | 11/1/1993 12 / No | Gasoline 10,000 | Fiberglass Reinforced Plastic None | Fiberglass Reinforced Plastic None | Pressurized | <div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div> | Yes Yes Yes Yes |
| 3 / 03 Currently in Use | 3176 | 11/1/1993 12 / No | Gasoline 8,000 | Fiberglass Reinforced Plastic None | Fiberglass Reinforced Plastic None | Pressurized | <div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div> | Yes Yes Yes Yes |
| 4 / 04 Currently in Use | 3177 | 11/1/1993 12 / No | Diesel 8,000 | Fiberglass Reinforced Plastic None | Fiberglass Reinforced Plastic None | Pressurized | <div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div> | Yes Yes Yes Yes |

Tank/Piping Release Detection Codes

| | | | | | |
|--------------------------------------|----------------------------|---------------------------|---------------------------------------|------------------------|---------------------|
| A Manual Tank Gauging | C Inventory Control | E Vapor Monitoring | G Interstit. Dbl-Wall Monitor | I SIR | K Deferred |
| B Tank/Line Tightness Testing | D ATG/Auto Line LD | F GW Monitoring | H Interstit. Sec. Con. Monitor | J Other Methods | L Not Listed |